



STEP5



- ⑦ Control Box * 1
- ⑧ Handset * 1
- ⑨ M4×12 Screws * 2

STEP6



- ⑨ Wires * 2
- ⑩ Cable Clips * 5


Ready To Use

Before Plugging the table into the outlet, make sure that

- The lift columns are level and set at the lowest position.
- All the screws are tightened, to avoid the desk making noise and wobbling.

Activate the desk by following the next steps.

- Please press button down and hold for 10-15 seconds until it stutters and beeps.
- Release the button, then your desk is ready to use.



Operation Guide

1. Memory desired height

- Press button "M", display show "S-" with flash.
- Press number and set desired position.

2. Advanced Safety feature- lock and unlock the table.


- Press button up and down at same time for 5 seconds, display "LOC"
- All single button will be inactive and table will be unable to move.
- Pressing button up and down together will unlock the keypad and release the LOC

3. Reset the table

When display show Error code or RST, Please reset the table.


- Unplug the power cord from the control box.
- Unplug the cable that links the keypad to the control box.
- Wait 30 minutes and plug all the cables in again.
- Do the reset: please press button down and hold for 10-15 seconds until it stutters and beeps.

If the keypad displays HOT, please unplug and replug and let it cool off for a couple of minutes before proceeding again.



Press by holding
10-15 seconds

Assembly Instruction



-Office Desk
-Electric lifting table










Installation tips




Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other .

Lay a mat or old blanket out to assemble onto so the floor and the furniture doesn't get scratched or damaged during building.


Part List

				
Lift Column*2	Crossbar *4	Base*2	Side Bracket*2	Crossbar Center Rails*2
				
Leveling Studs*4	Control Box *1	Handset*1	Wires*2	

Accessory Kit


				
Qty *16 M6×12 Screws	Qty *8 M6×16 Screws	Qty *4 M6×8 Screws	Qty *12 M5×18 Screws	Qty *2 M4×12 Screws
				
Qty *5 Cable Clips	Qty *12 Washers	4mm Allen Wrench		

STEP 1:




① Lift Column	* 2
② Crossbar	* 4
⑤ Crossbar Center Rails	* 2
Ⓐ M6×12 Screws	* 8

STEP 2:




① Lift Column	* 2
③ Base	* 2
⑥ Leveling Studs	* 4
Ⓑ M6×16 Screws	* 8

STEP 3:



④ Side Bracket	* 2
Ⓒ M6×8 Screws	* 4
Ⓔ Washers	* 12

STEP 4:



Ⓐ M6×12 Screws	* 8
Ⓓ M5×18 Screws	* 12